ATTACHMENT TO AGENDA ITEM

Ordinary Meeting 21 April 2015

Agenda Item 5.1	Craigmuir Lake		
Attachment 1	Craigmuir Lake - Petition	174	

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.

ADDDECC

- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The Irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.

 | Kolumna Della | Columna Della | Col
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the
 Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers
 to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

We the undersigned agree with the points made above and would ask that this neglected asset be brought up to a standard similar to Victoria Park Lake and Kialla Lakes.

CICNATIIDE

ADDRESS	SIGNATURE	
240 Echyca Rol	Poud	
236 Edwa Rol	advame	
236 Echuca Rol	Molline	•••
234 Echnica Rd	L'hamo-ale	1
R 242 ECHLUCA RD	ge-	
200 Echuca Rol	3 Brown	
52 O'BRIEN ST	Subtowell	
250 ELHUCA RS	Gang Bren	
250 Echuca Rd	Harrya Zhorra	
5 Kalimna Drive	6	
	236 Echera Rol 236 Echera Rol 234 Echera Rol 242 Echlua Rol 260 Echlua Rol 520 BRIEN ST 250 ECHLUA Ro 250 ECHLUA Rol	236 Echera Rd Jamp Brews 236 Echera Rd Shannovale 234 Echnica Rd Shannovale 242 Echnica Rd Brown 520 BRIEN ST SWHOWELL 250 ECHNICA RD Yang Brown 250 Echnica Rd Yang Brews 250 Echnica Rd Yang Brews

NAME

TO GREATER SHEPPARTON CITY COUNCIL

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.

ADDRESS

- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the
 Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers
 to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

We the undersigned agree with the points made above and would ask that this neglected asset be brought up to a standard similar to Victoria Park Lake and Kialla Lakes.

SIGNATURE

Linda Pearce 4 Arrangmith Cr. Mooroopha L. Deane
Robert Pay 10 Dennison Strom Holvert MPan
Vick Pay 10 Dennison st 14000 flots Pany
Marion Fry B Mundoona Crt. M/Pra slefer.
Bad Panethieri 15 Mundona art Blanett.
GRECKISATING 2 MACKINAR CAIS MORRORMA LASTON
Darette Lanov 27 Varymuir Due Ma Thehan
Suzanne Brown 7 Angs Crt Moorsopna du Bu
Ros Brown 7 ANGUS CT MOGROOFNA DE

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.
- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the
 Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers
 to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

NAME	ADDRESS	SIGNATURE	
SAUDRA	McNamara 4 Muna	Loona of Gangle Dan	
	NAMARA 4 MUNDOC	/ //	L.
		ignioir Drive. July am	t
		aconis Drive Premit	
Dova	(Aust) 26 C/	enginer Drive Dital	-
	")"""""""""""""""""""""""""""""""""""""	gramor Denot - 121	
		ma Crt Moorocona Alla	
Don	WRIEN 16 MWG	bons Car Moureopus PT	
Amber		ma cit Morcoma assurage	
Color		cona Oct Mooroopia Studiest	

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- · The drains are largely blocked in that area too.
- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the
 Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers
 to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

NAME AI	DDRESS	SIGNAT	URE //
KURT SZELPUK	14 W/NDLF/55	JUEN UE 3629	
toel Stephe			Soll
Judy Lloyd	21 Kalimna Dr.	. Mas100pn/	Aldoyd
JOHN CHAPPLE			
ELID CKAPPUL	2 CANDER STRE	167 Macopra Gi	Johnson .
MUSTAFA CENGIZ	8 LAYEVÍ	EW PLACE	themal (
RODNEY CHAMPINA	ESS, 6 Mundo	ma Oct, Modoofna	RD Champon
WAYNE TONKES,	3 Mundoona	CRT Movo	opner. an
BRONWYN DUNCAN	3 Mundoora (Crt Mona	Buran
Saah Fridd 58	: Kalimna Dr	Mascaspia Je	
Shirley Mudsan	5-/1 (< al.	mna Dvive	S. Muchan

To GREATER SHEPPARTON CITY COUNCIL

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.
- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

NAME	ADDRESS	SIGNATURE
MIGRID MANGER	7 MUNDOONA CRI MOOROOPN	4 Inguid Mauger
LYN CHAMPANES	6 MUNDOONA SAI MOONE	DAAA 1
	40 KALIMAN DRVedboor	
, ,	40 KOLIONA DRVELOOU	. / 7
	15 KAUMUA DRIVE, MOOROGANA	767
	ser 18 Krziman DIL Mac	. 1/10.1
X	5 MUNDOONA (R7 MO)(00)	AAA IA
•••••	12 MUNDOONA CRT ME	()
	ROTHEY PARK VILLAGE MO	11.11.
Jay Doncer	58 talimna Dv.	Markopy (Spann)

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.
- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a tollet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the
 Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers
 to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

NAME	ADDRESS	SIGNATURE
Neil Gi	iffiths 3 Kolimna D. Mocoopna	eseel Juffe L
DANYL	ELENDER 1/1 KALIMNA Ar MOOROO	ONA SHE
ER	Howell y Kalimna	11. ER. Housell
R.D.	HAMER GKALIMNAD	VE 12 Dames
WP	CHESSELLS 11 Kalimna	Dr Wellerulls
alu	- E Hausen 11 KALIMN	A DR Quen & Hamson
Olvi	ia M. Muchan 6/1 Kalimana	Dive BI 16 Nickan
Clobert	6 Lought 15 WALIMA	in Dre . (Solut & Langton
TROY	PIERCE 17 KALIMNA	DRIVE Ty Pun
Tampe	A-SPEECHLY 19 KALIMNA	DRV METGE
***************************************		7

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.
- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the
 Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

NAME	ADDRESS	SIGNATURE	
reles.	Dow 14 crojamus Dr	· Maorooppe	Thomas
Sarah	Neek A Craigmun dry Mi		
Rudg	Schwarschnik 4	Craig Mur P	5 Rallow D
Inda.	of Yims 258 ECH	West PAD MOR	00212 NA
Jenn	y Locke 16 Gaignuir	Dre Moorooping (Ze.
and the second second second second second second	2 HE Walned in		2,
NAVILLE	SIMKIN 24 CRAILM	UR ORIVA	NS inter
STAN N	NINE 22 CRAISMUIR DA	TYE MORCORT	9 84/L
Colleen	Milie 22 Craigmuir I	one Mooreophi	2 \ A : [li <
Dean 1	SHARY 20 Craigmin D.	nie Mooroopia	Hadelle
	1		\vee

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.
- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the
 Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers
 to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

NAME	ADDRESS			SIGNATURE	
Terry Allen	33 Kaji	mma 17r	MOSROEPAA	J Sthere	
Kyal cruickshan	ks 23	Kalimua D	nrive '	ph.	
Terry Albert Kyal croickshow C. Cledhill	13	Kal mure	Dre.	Kale	
		_			***************************************
	20				
,		+			
	***************************************	25			
					. = .:
1				*	
		· X			

TO GREATER SHEPPARTON CITY COUNCIL

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.
- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

We the undersigned agree with the points made above and would ask that this neglected asset be brought up to a standard similar to Victoria Park Lake and Kialla Lakes.

SIGNATURE

NAME	ADDRESS	SIGNATURE
Judy LL	oyd 21 Kalinno t	11. Mooreogna Judy Lloyd
Joenah Lo	nghran 20 Kalinuc	a Drivo
Barton Die	Je KALIMAR	NE Mysselpais Sa D. Jones
Malcolm	Bugen 31 KALIMARA	DVE MOOROSPNA ME Buyen
BARBHRA J.		a DRIVE MOSROSPINA D. J. Proff ()
Helen Wre	of 24 Kaleman D	r clooroopna Livrett
JUANB	RAGGS 13 WINDLA	4SC AVE
GREH of	YONDA KEELAN 27 6	CALIMNA DRIVA
aft	Bren. 29 KAL	IMNIS DR. NOUR SOL
		,

NAME

To GREATER SHEPPARTON CITY COUNCIL

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialia Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.

ADDRESS

- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the
 Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers
 to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

We the undersigned agree with the points made above and would ask that this neglected asset be brought up to a standard similar to Victoria Park Lake and Kialla Lakes.

SIGNATURE

Rence Durward I Windlass Ave moorcopy &
Terry Durewed 1 windlass Ave MOOROOPNA ISO
NEIL HUGHES TO GILLIESTON COURT MOROODNA WITH
ANNE I DON ELLIS 4 GILHESTON CRT. MODROOPNA DON ELL
Jason Hughes 12 Baker crecent Moorooma Studies
BRIAN MOYCAN IN CONNIST LO MIDNO ME
DAMIAN MUKAHY SIG VERNEY RD SHEPP NORTH DUMMY

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.
- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

highlighted

We the undersigned agree with the points made above and would ask that this neglected asset be brought up to a standard similar to Victoria Park Lake and Kialla Lakes.

CICNIATUDE

NAME		ADDRESS		SIGNATO	A4 //	
Diana C	Siacomelli	5 Kaeila	COVA, Mooro	yna	Majoria	<u></u>
Andrew	Ryssell	5 Kacila	COUPT, MOORE	orna	1 00	000
Shude	y Hughes	10 6 1/1	eston Crb	Mooi	rooku o	013000
	***************************************					•••••
		••••••		*****************		

IF YOU WIEH TO SIGN PLEASE PETORNTO 3 KAUMINA DRIVE MOORCOPINA

TO GREATER SHEPPARTON CITY COUNCIL

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.
- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the
 Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers
 to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

NAME	ADDRESS	SIGNATURE
DINNE MIL	ET 2 KABUA OLT MOOROOF	is Geral Cylor.
Maddie	SPILICK 2KAEILACK MI	2P NAME
	Aylett 2 Kaeila Crt Mars	
Justin	Aylor 2 Kacila CV+ Mo	ovorgence Justin Aglett
Ladhy A	GIETT 2 KAEILA CET MO	ORDONA Ragett

:		

IF YOU WINTO-KIN - PLEASE RETURN TO 3 KALIMMA DRIVE MODEROPHON

To GREATER SHEPPARTON CITY COUNCIL

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.
- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the
 Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers
 to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

NAME	ADDRESS		SIGNATURE	
Megan Walker	5 Craignair	Drive	SIGNATURE Meyn Walker	
			2	

TO GREATER SHEPPARTON CITY COUNCIL MOORGOFFINA

We the undersigned want to bring to your attention the state of Craigmuir Lake and its surroundings. We see how nice the surroundings are at the Victoria Park Lake and Kialla Lakes are kept and would like to see improvements around the Craigmuir Lake on Echuca Road. The following points are brought to your attention for your consideration and hopefully action.

- The neglect of the trees, shrubs and grasses planted around the lake particularly the ones along the areas
 not bordered by private homes along the edge of the lake such as Lake View Place. Many have died due to
 incorrect planting and little or no care has been given to them after planting.
- The drains are largely blocked in that area too.
- If this area is intended to encourage visitors coming into Mooroopna, or even for locals to use, a toilet block is needed.
- If the storm water piping in the new estates to the West were connected to the lake it may not be necessary
 to fill the lake from the Goulburn river system. This was mentioned several years ago to a council official but
 was ignored.
- With the new houses being built on the lake and the state of the land on the estate it really detracts from the beauty of the lake.
- The irrigation system to fill the lake is a disgrace and needs a fence around it to stop children climbing on to that area as it is highly dangerous.
- Lights are needed at the corner of Craigmuir Drive and Echuca Road as it is very hard for cars to see the
 Craigmuir Drive sign at night and when walking in early morning and evening not enough lighting for walkers
 to see the footpath.
- Walking paths need to be repaired and made safer for those who walk around the lake and the new subdivisions. A lot of elderly people use this for daily walking and is highly dangerous in some spots.

NAME	ADDRESS	SIGNATURE
Cou, w hy	TTECHES 32 CRAIGMUIR DRIVE MODILOOPNA	6 pers
	JHITELAN 32 CARIGNUIR DRY MOOROOPNA	Q. 200

<i>,</i>		
